CORRECTLY MANUFACTURED SURFACE SWIMMERS HARNESS CHEST STRAP



IMAGE 1

CORRECTLY MANUFACTURED SURFACE SWIMMERS HARNESS CHEST STRAP




IMAGE 2

INCORRECTLY MANUFACTURED SURFACE SWIMMERS HARNESS CHEST STRAP




CORRECTLY MANUFACTURED SURFACE SWIMMERS HARNESS CHEST STRAP



The fixed sewn chest strap webbing is correctly sewn directly to the first vertical metal bar from the tip of the lifting v-ring.

INCORRECTLY MANUFACTURED SURFACE SWIMMERS HARNESS CHEST STRAP



The fixed sewn chest strap webbing is incorrectly sewn to the back end of the lifting v-ring. The arrow points to the vertical metal bar that the fixed chest strap webbing should have been sewn around.